

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent

Patent No.: 7,590,251

Inventor: Jack B. Andersen et al.

Issue Date: September 15, 2009

Appln. No.: 10/805,588

Filed: March 19, 2004

Title: CLIP DETECTION IN PWM AMPLIFIER

Conf. No.: 9255

Art Unit: 2614

Examiner: Suthers, Douglas John

Atty. Docket No.: ELAN-01192US1

**Customer No.: 23910**

**REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR §1.322**

Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

It is hereby certified that a certain error appears in the above-identified U.S. patent. The requested correction is being made to correct an error in the claims of the patent and is presented on the attached PTO/SB/44 form.

Pursuant to 37 C.F.R. § 1.322(a)(1)(i), the undersigned attorney of record, as a representative of the patentee or the patentee's assignee, requests that a Certificate of Correction be issued.

No fee is believed due in connection with this paper. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1326 for any matter in connection with this paper, which may be required.

Respectfully submitted,

Date: October 5, 2009

By: /Jeffrey R. Kurin/  
Jeffrey R. Kurin  
Reg. No. 41,132

FLIESLER MEYER LLP  
650 California Street, 14<sup>th</sup> Floor  
San Francisco, California 94108  
Telephone: (415) 362-3800  
Facsimile: (415) 362-2928